

# M3s 1.40 版固件

2018 年 3 月 15 日更新

## 修改内容:

- 1、修复了部分品牌内存卡偶尔不能识别的问题。
- 2、修复部分 WAV 格式文件播放全是噪音的问题。
- 3、修复切换为繁体时，多国语言列表中“简体”两字仍显示为繁体的问题。

## 系统更新方式:

- 1、前往山灵官网产品页面下载最新固件 **update.upt**。
- 2、确保播放器电量充足，将压缩包解压打开，把压缩包中的 **update.upt** 升级文件放入 TF 卡中。
- 3、在系统设置中，选择系统升级，升级完成后系统自动重启，升级完毕。
- 4、如在升级过程中把卡拔出，机器会显示 **insert TF Pls** 的字样，此时只需要把卡重新插入就可以继续升级了。
- 5、如选择系统升级后提示未发现升级文件，请检查是否解压了压缩包、升级文件是否放在根目录或查看升级文件在传输过程中有无损坏，升级文件 **update.upt** 需放在内存卡根目录下，如升级文件在传输过程中损坏，请把升级文件重新导入内存卡。

# M3s V1.40 Firmware

Mar.15th,2018.

## Changes and fixes:

1. Fixed the problem of micro SD card not being recognised.
2. Fixed the problem of WAV playback.
3. Fixed the problem of Chinese language setting.

## How to update:

1. Go to the page of M3s on Shanling official site to download the latest firmware.
2. Make sure that M3s is in full battery condition, unzip the file and put update.upt into root folder of TF card.
3. Choose “System Update” in system settings and wait until system restarts. Check in settings “About M3s” to be sure new firmware is installed.
4. If TF card has been pulled out during update process, it will show “insert TF Please” , please insert TF back into your device in order to continue update.
5. If update doesn't start after choosing “System Update” , please check if the file has been unzipped, if the file has been in root folder, or if the file has been damaged during the transfer. The firmware must be in the root folder of TF card. If it is damaged, please transfer it into the TF card again.